APP-00779

GOREANGAB WATERFRONT SERVICE STATION ENVIRONMENTAL MONITORING SUMMARY REPORT 14 FEBRUARY 2017 TO 29 FEBRUARY 2020



Compiled by: Compiled for:



True-Gem Investments CC

Project	GOREANGAB WATERFRONT ENVIRONMENTAL MONITORIN FEBRUARY 2017 TO 29 FEBRUARY	G SUMMARY REPORT: 14		
Report Version/Date	Final Feb 2020			
Prepared for:	True-Gem Investments CC P.O. Box 50088 Bachbrecht Windhoek Namibia			
Lead Consultant	Geo Pollution Technologies (Pty) Ltd PO Box 11073 Windhoek Namibia	TEL.: (+264-61) 257411 FAX.: (+264) 88626368		
Main Project Team	André Faul (B.Sc. Zoology/Biochemistry); (B.Sc. (Hons) Zoology); (M.Sc. Conservation Ecology); (Ph.D. Medical Bioscience)			
Cite this document as	Faul A. 2020. Goreangab Waterfront Service Station Environmental Monitoring Summary Report: 14 February 2017 TO 29 February 2020			
Copyright	Copyright on this document is reserved. No part of this document may be utilised without the written permission of Geo Pollution Technologies (Pty) Ltd.			
Report Approval	André Faul			

I <u>bradley loane basson</u> CC, hereby confirm that we approve the document. All material information in the position	_ acting as the representative of True-Gem Investments Environmental Monitoring Report as presented in this ssession of the proponent that reasonably has or may have
1 · · · · · · · · · · · · · · · · · · ·	is consider of the proportion that reasonably has of may have
bearing on the report was provided to the con	sultant.
Signed at Wind hoek Trae-Gem Investments CC	on the 06th day of March 2020. CC 2011 1971 Company Registration Number / ID

TABLE OF CONTENTS

1	IN	VTRODUCTION	. 1
2	ΡI	LANNING PHASE	. 1
2.1	l	COMPLIANCE	. 1
2.2	2	APPOINTMENTS	. 1
2.3	3	MANAGEMENT	. 1
2.4	1	RESTORATION FUND/INSURANCE	. 1
3	O	PERATIONAL PHASE	. 1
3.1	l	EMPLOYMENT	. 1
3.2	2	SKILLS, TECHNOLOGY & DEVELOPMENT	. 1
3.3	3	HIV/AIDS	. 2
3.4	1	TRAFFIC	. 2
3.5	5	Fire	
3.6	5	HEALTH, SAFETY AND SECURITY	. 2
3.7	7	VISUAL	. 2
3.8	3	Air Quality	. 2
3.9)	Noise	. 2
3.1	0	Waste	. 2
3.1	1	GROUNDWATER, SURFACE WATER AND SOIL CONTAMINATION	. 2
3.1	12	ECOLOGICAL	. 2
4	M	AINTENANCE PHASE	. 3
5	D	ECOMMISIONING PHASE	. 3
6	C	ONCLUSION	. 3

1 INTRODUCTION

True-Gem Investments CC obtained an environmental clearance certificate on 08 October 2013 for the construction and operations of a fuel retail facility on erf 77 GG, Eveline Street, Goreangab in Windhoek. The original environmental clearance certificate was renewed in 2017 and the renewed document was issued on 14 February 2017. The facility, known as Goreangab Waterfront Service Station, has three underground storage tanks of 46 m³ each. One stores unleaded petrol and two diesel. During the validity of the environmental clearance certificate, typical tasks associated with fuel retail facilities were performed. This mainly involved the receipt of fuel from road tankers, storage of fuel in underground storage tanks and dispensing of fuel to clients. Daily tank dips and fuel volume reconciliations are conducted and the site is also cleaned and maintained regularly.

This report provides a summary of all monitoring during the period 14 February 2017 to 29 February 2020.

2 PLANNING PHASE

The following planning phase results are based on the requirements of the EMP.

2.1 Compliance

The facility has an environmental clearance certificate (Appendix A) and an existing petroleum retail licence as issued by the Ministry of Mines and Energy, Directorate Petroleum Affairs (Appendix B).

2.2 Appointments

All employment contracts (employees and contractors) are available on file.

2.3 Management

The health, safety and environmental (HSE) coordinator for the facility is Edwin Basson. The appointed site manager for the duration of reporting was Genevieve M. Agnew. During the monitoring period the HSE and manager ensured that:

- The facility continues to adhere to South African National Standards (SANS) as prescribed by the Petroleum Products Act.
- All personal protective equipment (PPE) requirements were clearly stipulated to contractors and personnel entering the site.
- The contact details of all emergency services were displayed in a visible and easily accessible location at the facility.
- The facility has a Health and Safety Management System as well as complies to the Environmental Management System of the fuel supplier, Puma Energy Namibia.

2.4 Restoration Fund/Insurance

Insurance for spill clean-up typically lies with the petroleum supply company.

3 OPERATIONAL PHASE

The following operational phase monitoring are based on the requirements of the EMP.

3.1 Employment

Goreangab Waterfront Service Station employs 60 people all of whom are Namibian citizens. They are 37 male employees and 23 female. The employee base is responsible for various tasks ranging from the pump attendants to the shop personnel and management.

3.2 Skills, Technology & Development

Where new staff were appointed, on-the-job training was, and continue to be, provided for day to day tasks. All specialist work are outsourced to established contractors where the necessary skills is not available internally. Training is provided to ensure safe operations.

3.3 HIV/AIDS

Social responsibility forms part of the on-the-job training which includes informative talks. Personnel are encouraged to maintain a healthy lifestyle.

3.4 Traffic

No traffic related incidents were reported and no complaints from the surrounding community were received. On average 16 tanker trucks visit the site monthly for fuel deliveries.

3.5 Fire

No fire related incidents occurred during the monitoring period. Fire extinguishers are placed at strategic locations throughout the facility and within easy reach of pump attendants. Firefighting equipment are serviced or replaced according to the prescribed intervals. A register of servicing of equipment is available on file. Emergency shutoff systems are in place to minimize the risk of fire.

3.6 Health, Safety and Security

All employees are provided with the required PPE and safe equipment handling training (ongoing in-service training). No health and safety related incidents occurred during the validity of the ECC. No threats to the security of the premises occurred.

3.7 Visual

No complaints were received from the surrounding community regarding the aesthetic appearance of the site.

3.8 Air Quality

The storage tanks are properly vented and some vapours are released during filling. However, the vents are situated in such a way that limits air quality deterioration. No air quality related complaints were received.

3.9 Noise

Fuel retail facilities are operational 24 hours a day, seven days a week. Some noise are produced as a result of vehicles accessing and leaving the site. No noise related complaints were received from the surrounding community.

3.10 Waste

All domestic waste was regularly collected and discarded at an approved waste disposal facility by the Municipal waste collection services. No hazardous waste was produced that required disposal and no complaints were received from the surrounding community regarding any waste related impacts such as bad odours, windblown waste items such as paper, or unsightly (e.g. overflowing) waste bins.

3.11 Groundwater, Surface Water and Soil Contamination

The facility is approximately three years old and was built to SANS standards with the proper composite tanks with inspection holes in the tank pits. No fuel spills leading to groundwater or surface water contamination occurred during the monitoring period. Where minor spills, such as during overfilling of a vehicle occurred, the fuel was prevented from reaching sensitive receptors by the concrete slabs with drains leading to an oil water separator. Such spills were also cleaned as soon as possible. Regular tank dips and fuel volume reconciliation were performed. No significant losses that may indicate a fuel leak were detected.

3.12 Ecological

The facility is located in a disturbed urban setup. No extraordinary animal sightings were made during the monitoring period. Nesting of birds are actively discouraged.

4 MAINTENANCE PHASE

No significant maintenance other than day to day maintenance activities were performed for the reporting period. Some construction activities related to the installation of grid tied photovoltaic panels on the roof by an external contractor.

5 DECOMMISIONING PHASE

No decommissioning activities were performed for the reporting period.

6 CONCLUSION

For the duration of the validity of the environmental clearance certificate, normal operations associated with a fuel retail facility continued. No known significant fuels spills or health and safety related incidents occurred. No complaints were received from neighbours or community members during the reporting period. Goreangab Waterfront Service Station has a Health, Safety and Environmental Management system in place to ensure potential impacts of the facility is prevented or mitigated.

It is recommended that the environmental management plan be considered for improvement of environmental monitoring processes and that record is kept of all training provided. This can be in the form of signed attendance sheets for regular toolbox talks, firefighting training, first aid classes, etc.

Appendix A: Environmental Clearance Certificate



MINISTRY OF ENVIRONMENT AND TOURISM

Tel: (00 26461) 284 2111 Fax: (00 26461) 229 936

E-mail: johannes.hambia@met.gov.na

Enquiries: Mr. J. Hambia

Cnr Robert Mugabe & Dr Kenneth Kaunda Street Private Bag 13308 Windhoek Namibia

14 February 2017

OFFICE OF THE ENVIRONMENTAL COMMISSIONER

Attn. Bradley Basson True-Gem Investment cc P. O Box 50088 Windhoek Namibia

Dear Sir or Madam

SUBJECT: ENVIRONMENTAL CLEARANCE CERTIFICATE FOR THE PROPOSED PUMA ENERGY FUEL RETAIL FACILITY ON ERF 77, EVELINE STREET, WINDHOEK, KHOMAS REGION

The Environmental Management Plan submitted is sufficient as it made an adequate provision of the environmental management concerning proposed activities. From this perspective, regular environmental monitoring and evaluations on environmental performance should be conducted. Targets for improvements should be established and monitored from time to time.

This Ministry reserves the right to attach further legislative and regulatory conditions during the operational phase of the project.

On the basis of the above, this letter serves as an environmental clearance certificate for the fuel retail facility to proceed. However, this clearance letter does not in any way hold the Ministry of Environment and Tourism accountable for misleading information, nor any adverse effects that may arise from this project activity. Instead, full accountability rests with True-Gem Investment cc and its consultants.

This environmental clearance is valid for a period of 3 (three) years, from the date of issue unless withdrawn by this office.

P/Bag 13308

2017 -02- 17

Office of the

Yours sincerely,

Teofilus Nghitila

ENVIRONMENTAL COMMISSIONER

"Stop the poaching of our rhinos"

All official correspondence must be addressed to the Permanent Secretary

Appendix B: Fuel Retail Licence



MINISTRY OF MINES AND ENERGY

PETROLEUM PRODUCTS AND ENERGY ACT, 1990 PETROLEUM PRODUCTS REGULATIONS (2000)

RETAIL LICENCE

[Regulation 5(4)]

	[Regulat	ion 5(4)]		
RETAIL LICENCE		Licence No. R/433/2014		
Name of licence-holder Tru-C		Gem Investments CC 2011/1971		
Address of licence-holder	Physical Address Postal Address		Postal Address	
	Erf 77 GG, Goreangab Windhoek Namibia		P.O Box 50088 Bachbrecht Windhoek Namibia	
Name of Retail O	utlet	Goreangab	Waterfront Service Station	
Name of Supplying Wholesaler		Puma Energy Namibia (Pty) Ltd		
Premises to which lices	nce relates	Erf 77 GG S 22° 31′ 30°′		
Conditions applicable to licen See overleaf of page for general of		ns applicable to lic	ence.	
Date of issue of licence		22 July2014		
Issued by the Minister of Min 22 July 2014 at Windhoek Minister: Mines and Energy	es and Energy in	OFFI	HSTRY OF MINES AND ENERGY Official Stamp (for office use) PRIVATE BAG 13297 WINDHOEK	
w ⁵⁶ &			OFFICIAL	

CONDITIONS APPLICABLE TO RETAIL LICENCE

General conditions

- The retail licence-holder must at all times comply with the Petroleum Products and Energy Act and Petroleum Products Regulations (2000) and all other applicable laws, including laws relating to labour, safety, hazardous substances, security, health and environment.
- 2. The retail licence-holder must inform the Minister as soon as practicable of any dangerous situation arising from the conduct of activities authorised under the retail licence including the steps taken or proposed to be taken by the licenceholder to rectify such situation or to eliminate or minimise the danger arising from such situation.
- The retail licence-holder must keep such records and must submit such information to the Minister as required by or under the Petroleum Products Regulations (2000).
- The retail licence-holder must comply with all provisions of the Petroleum Products Regulations (2000), relating to petroleum products spills.
- The retail licence-holder may not abandon the licensed premises otherwise than in accordance with the Petroleum Products Regulations (2000).
- Petroleum products sold to consumers must comply with approved specifications made applicable under the Petroleum Products Regulations (2000).
- The retail licence-holder must at all times hold such permits, licences and certificates relating to the sale of petroleum products and other services provided at the retail outlet, as may be required by any other law.
- The retail licence-holder may not obtain fuel by means of wholesale sale for purposes of retail sale from any person other than a wholesale licence-holder.

Special Conditions