

This land rehabilitation and restoration initiative is integrated into the Draft Henties Bay Urban Development Structure Plan, submitted for approval to the Urban & Regional Planning Board, ensuring alignment with long-term urban planning objectives.

Figure 2: Decommissioned & Rehabilitated Building Rubble Dumpsite, Henties Bay, Namibia



This image depicts the current state of the site post-initial refilling with sand, showing rehabilitated areas. Coordinates: Centroid $-22.107747, 14.283326$. Source: Erongo Consulting Group, 2025

Figure 3: Locality of Henties Bay (Project Area).




Figure 4: Aerial photography of the Building Rubble Dumping Project, illustrating the current state of the dumpsite, including waste piles and disturbed land. Coordinates: Centroid –22.107747, 14.283326. Source: Erongo Consulting Group,

